

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil by the Gas Lift Compressor, see photo 2		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."		Date: 09/23/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:

Type			corrective date
Vertical Separator	# 3		
Comment:			
Corrective Action:			Date:
VRT	# 2		
Comment:			
Corrective Action:			Date:
Emission Control Device	# 6		
Comment:			
Corrective Action:			Date:
Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:			Date:

Type: Flare	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Methanol Tanks/Pumps		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Blow cases		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Sand Trap		
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares Berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	16	500 BBLs	STEEL AST		40.587800,-104.524990
Comment:					
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 431056 Type: LOCATION API Number: - Status: AC Insp. Status: AC

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 08/14/2019 at approximately 15:34, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC, Shable AB 11 Econode, at Location ID #431056 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Stained Soil by the Gas Lift Compressor, see photo 2. Comply with Rule 907.e. Corrective Action date of 09/23/2019 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspection.</p>	petrie	08/21/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402151498	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915623
696300512	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915620