

# Inspection Photos

API: 05-041-06065

Operator: ULTRA RESOURCES INC

Inspection Date: 8/27/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 1.** Facing south at the beginning of the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 2.** There is no outlet protection at the outlet of the culvert and signs of erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 3.** There is an erosion channel along the access road as it ascends the hill.



## Inspection Photos



**Photo 4.** The sides of the access road as the road ascends the hill are not stabilized and no BMP's are present.



## Inspection Photos



**Photo 5.** Facing south further along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 6.** Facing southwest along the reclaimed access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 7.** This area along the access road has not reached 80% vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 8.** Facing south toward the location. Red arrow points to well marker.



## Inspection Photos



**Photo 9.** This area at the location has not reached 80% vegetation cover. Red arrow points to well marker.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 10.** Facing north at the east side of the location. Vegetation is well established in this area. Red arrow points to well marker.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 11.** Facing north at the west side of the location. This area at the location has not reached 80% vegetation cover. Red arrow points to well marker.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 12.** Facing southeast at the disturbance area northwest of the well site. Red arrow points to well marker.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-041-06065 | Date: 8/27/2019

## Inspection Photos



**Photo 13.** Facing north toward the surrounding undisturbed reference area.

