

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

08/22/2019

Document Number:

689802936**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 312758 Waldron, Emily 2A Doc Num: _____

Operator Information:OGCC Operator Number: 82440Name of Operator: STEHLE OIL COMPANYAddress: P O BOX 1577City: CRAIG State: CO Zip: 81626**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments9 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Stehle, Cary	(970) 824-6909	carystehle@gmail.com	
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222189	WELL	SI	11/01/2018	OW	081-05136	ILES INVESTMENT CO 1-23	SI

General Comment:

COGCC Inspection Report 689802936 Summary

On Monday 07/15/2019 at approximately 11:15, I, Inspector Emily Waldron, conducted a field inspection at Stehle Oil Company Iles Investment Co 1-23, at 05-081-05136 in Moffat County Colorado.

While there, I performed a follow up inspection to inspection report 689801290. No corrective actions from that report have been performed.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	At entrance.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	01/03/2014
Type	TANK LABELS/PLACARDS		
Comment:	Sign not posted or information inaccurate on tanks or containers.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/03/2014

Emergency Contact Number:

Comment: 970-824-6909

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment. 1 unused 3" steel riser observed in pit not marked for abandonment or locked out tagged out. 3 unused 3" steel risers observed at tan tank cluster (40.31086, -107.67829) not marked for abandonment or locked out tagged out. 1 unused 2" steel riser observed at tan tank cluster not marked for abandonment or locked out tagged out. 1 unused 3" steel riser observed at white tank (40.31084, -107.67812) not marked for abandonment or locked out tagged out. 2 unused 3" steel risers and 1 unused 2" steel riser observed at entrance (40.31051, -107.67846) not marked for abandonment or locked out tagged out.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/11/2018
Type	WEEDS		
Comment:	Noxious and annual weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/06/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: All spills and releases mentioned in previous inspections remain unresolved. Operator has not contacted COGCC EPS.

☒ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1				,
Comment: Stained soil and leaks observed at tank base.					
Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.					Date: 07/21/2016

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Inadequate berms around tank(s).				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 07/21/2016

Contents	#	Capacity	Type	Tank ID	SE GPS
	3		STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Inadequate berms around tank(s).				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 07/21/2016

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	222189	Type:	WELL	API Number:	081-05136	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type:

Liner Condition:

Comment: Netting or fencing not maintained, gaps exist around perimeter.

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment: Netting or fencing not maintained, gaps exist around perimeter.

Corrective Action

Date: 07/03/2018

Anchor Trench Present:

Oil Accumulation: YES2+ feet Freeboard: NOComment: Oil on pit, less than 2 feet of freeboard, no permit on file.

Corrective Action

Date: 06/22/2016

Lower fluid level so at least two feet of freeboard exists per Rule 902.b.
Remove oil from pit per Rule 902.c.
Submit an eForm 15 Pit Report to update COGCC records with current information.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402152672	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916776
689803003	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916770