

Inspection Photos

Loc#451938

Operator: Sandridge

Inspection Number: 692401289

Inspection Date: 8/15/19





Photo#1:
Overview of Location to Northeast.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Beaver Creek Loc#451938



Photo#2:
Topsoil pile is weedy and not properly stabilized.



Photo#3:
Topsoil pile is weedy and not properly stabilized.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Beaver Creek Loc#451938



Photo#4:
Canada thistle established on site.



Photo#5:
Debris weeds on site.

August 15, 2019



Inspection Photos: Sandridge Beaver Creek Loc#451938