

Interim Reclamation and Stormwater Inspection

August 27, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 441199

Inspection Document #: 697500533

Weld County, CO

SENE Section 26 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WILSON RANCH /5C-27HZ
Location ID: 441199



Photo 1. Photo taken of the northeast battery location, facing North. BMP maintenance is required. Also, the installed stormwater BMPs do not appear to be installed with good engineering practices, as the check dams are spaced too far apart to slow the velocity of stormwater runoff. Photo also illustrates unmanaged weeds.

Inspection Photos
Location Name: WILSON RANCH /5C-27HZ
Location ID: 441199



Photo 2. Photo taken at the end of the stabilized channel, facing East. Photo illustrates erosion and BMP maintenance is required.

Inspection Photos
Location Name: WILSON RANCH /5C-27HZ
Location ID: 441199



Photo 3. Photo taken from the northern facility, facing North. Photo illustrates an unknown disturbance within the Interim Reclamation area where weeds are not being managed.

Inspection Photos
Location Name: WILSON RANCH /5C-27HZ
Location ID: 441199



Photo 4. Photo taken from the northern facility, facing East. See comments under Photo 3.