

Inspection Photos
Location Name: DF Ranch PC GK 09-99HZ
Location ID: 419856



Photo 1 – Pumping Unit




Photo 2 – Stained Soil at Wellhead approximately 12' x 6'

Inspection Photos
Location Name: DF Ranch PC GK 09-99HZ
Location ID: 419856



Photo 1 – Mechanical Conditions – Wellhead appears to be leaking onto the ground,

Photo 2 – Stained Soil at Wellhead approximately 12' x 6'