

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/24/2019

Submitted Date:

08/25/2019

Document Number:

688305675

FIELD INSPECTION FORM

Loc ID 434358 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10706
Name of Operator: D90 ENERGY LLC
Address: 202 TRAVIS STREET #402
City: HOUSTON State: TX Zip: 77002

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	COGCC Flowline Integrity
Spear, Sam	(970) 554-1988	sam@d90energy.com	All Inspections
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Kosola, Jason		jason.kosola@state.co.us	COGCC EPS
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434359	WELL	PR	06/11/2015	OW	073-06552	BIG SKY 5-11	SI

General Comment:

[Spill Inspection](#)

On 8/24/2019 at ~0930, operator contacted inspector about a flowline spill at the Big Sky 5-11 well of ~10-15 bbls. Free liquids were vacuumed into a truck, the spill was contained and well shut in. Inspector was told that the main office was completing the Form 19I and contracting the appropriate people (Lincoln County LGD and the land owner). It had rained the night before so oil, produced water and rain water were in the spill. A small area of the spill was outside the deadmen and in the adjacent fallow wheat field. An earthen berm was placed around the remaining spill that would be placed in a roll off on Monday or Tuesday and properly disposed of. The flowline would also be excavated and repaired. Gas was still bubbling from the flowline area next to the well but was diminishing. Possible cause of leak is pipe corrosion.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:
 Comment:
 Corrective Action:
 Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
PW/CO	WELLHEAD	>= 5 bbls	
Comment:	Flowline leak at wellhead. Operator immediately stopped and cleaned up free fluids and contacted COGCC inspector. See attached photos. Seventy-two hours for Initial Form 19 Report submittal and 10 days for Form 19S. Thirty days to remove stained soil.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>08/27/2019</u>

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		

Comment:		Date:
Corrective Action:		

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		Date:
Comment:		
Corrective Action:		

Flaring:

Type		Date:
Comment:		
Corrective Action:		

Inspected Facilities

Facility ID: 434359 Type: WELL API Number: 073-06552 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402154909	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4918708
688305676	D90 Energy Big Sky 5-11 Spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4918705