

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2019

Submitted Date:

08/27/2019

Document Number:

687905442

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325755 \_\_\_\_\_ Stewart, Joseph \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96735  
Name of Operator: WILLIFORD RESOURCES, L.L.C.  
Address: 6506 S LEWIS AVE STE 102  
City: TULSA State: OK Zip: 74136

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	<a href="#">e-mail receipient</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215338	WELL	PR	05/29/2003	OW	067-06943	FIELDS 1	PR

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign posted at pumpjack.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Contact information posted on sign.	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Prime Mover	# 1		
Comment:	Natural gas engine has stained soil around and underneath engine.		
Corrective Action:	Remove stained soil per Rule 1002.f.	Date:	09/27/2019
Flow Line	# 2		
Comment:	1-2" flowline from wellhead to offsite crude oil storage tank. 1-1" flowline from wellhead to pumpjack engine fuel gas.		
Corrective Action:		Date:	
Ancillary equipment	# 1		
Comment:	Wellhead has stained soil around it.		
Corrective Action:	Remove stained soil and dispose of properly per Rule 1002.f.	Date:	09/27/2019
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215338 Type: WELL API Number: 067-06943 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Secondary containment for 55gal drums.
Berms	Pass	Ditches	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402157270	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920857">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920857</a>
687905452	Inspection Photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920840">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920840</a>