

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2019

Submitted Date:

08/27/2019

Document Number:

693501192

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
318501 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 46290 _____
Name of Operator: KP KAUFFMAN COMPANY INC _____
Address: 1675 BROADWAY, STE 2800 _____
City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80202 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 _____ Number of Comments
5 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241422	WELL	PR	03/20/1995	OW	123-09211	ROBERT G BURGE 2	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 09/27/2019
Emergency Contact Number:			
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 09/27/2019
Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical Issue: 1" flow line on WH appears to be leaking		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 09/27/2019
Type	OTHER		
Comment:	Stained soil: stained soil around WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 09/27/2019
Type	WEEDS		
Comment:	Weeds in and around PU, electric panel and on location.		
Corrective Action:	Comply with rule 603 f		Date: 09/10/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Square tubing		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover # 1			corrective date
Comment:	Electric motor		
Corrective Action:			Date:
Type: Bradenhead # 1			
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Ancillary equipment # 1			
Comment:	Electric panel		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241422 Type: WELL API Number: 123-09211 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday August 27, 2019 at approximately 11:13 AM, I, Inspector Randy Silver, conducted an on-site inspection at KP Kauffman site Robert G Burg #2, at API # 05-123-09211 in Weld County Colorado. While there, I observed production well site During this inspection the following possible compliance issues were observed: Weeds: Rule 603 f Corrective action date of 9-10-19 See photos 1,2,4,5 Stained soil: Rule 907 e Corrective action date of 9-27-19 See photo 3 Well Head sign: Rule 210 e Corrective action date of 9-27-19 See photo 2 Mechanical issue: Rule 605 d Corrective action date of 9-27-19 see photo 3 At time of inspection well site appears not to have been maintained, weeds are overgrown in and around PU, Electric panel and location. Well head sign is faded and not legible. 1" flow line valve appears to be leaking causing the stained soil around well head. Weather conditions: Clear and location is dry. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	08/27/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402159027	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4922597
693501193	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4922591