

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2019

Submitted Date:

09/03/2019

Document Number:

687905474

**FIELD INSPECTION FORM**
 Loc ID 325164 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96735

Name of Operator: WILLIFORD RESOURCES, L.L.C.

Address: 6506 S LEWIS AVE STE 102

City: TULSA State: OK Zip: 74136

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214178	WELL	SI	02/01/2017	OW	067-05498	LONG & SCHLUTER 1	SI

**General Comment:**

This is a workover inspection with plugging operations currently being conducted in accordance with Form 6 Well Abandonment Report Doc#402009810

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted on location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead to be PA.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 214178 Type: WELL API Number: 067-05498 Status: SI Insp. Status: SI

**Workover**

Comment: Daily operations report:  
 8.29.2019-  
 \*Rig set up on location.  
 \*No pressure on tubing or casing.  
 \*A-Plus drilling pulled all rod and tubing with a total pipe tally of 3,380.47 feet of 2 5/8" tubing removed.  
 \*Round trip 4.5" mill to 3353'.  
 \*Set 4.5" Concrete retainer at 3353'  
 \*Pressure test tubing to 1000psig. (test fail)

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
Continue plugging operations on 8/30/2019.	stewartj	08/30/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905475	Location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4926951">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4926951</a>