

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2019

Submitted Date:

09/03/2019

Document Number:

687905476

FIELD INSPECTION FORM
 Loc ID 325164 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96735

Name of Operator: WILLIFORD RESOURCES, L.L.C.

Address: 6506 S LEWIS AVE STE 102

City: TULSA State: OK Zip: 74136

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214178	WELL	SI	02/01/2017	OW	067-05498	LONG & SCHLUTER 1	SI

General Comment:

This is a continued inspection for plugging operations of location from Inspection Report Doc#687905498 and in accordance with Form 6 Well Abandonment Report Doc#402009810

Inspected Facilities									
Facility ID:	214178	Type:	WELL	API Number:	067-05498	Status:	SI	Insp. Status:	SI
Workover									
Comment:	Daily operations report: *Plug #1 pumped 18 sxs cmt @ Dakota 3353'-3122' Tag @3226' *PSI test on casing (test fail) *Plug #2 pumped 18 sxs cmt @ Gallup Top 2576'-2345' displace with corrosion inhibitor. *Could not tag second plug due to cement to set up.								
Corrective Action:					Date:				