

Location Name: Coral Production Corp. - Peterson E-2  
Inspection Date: 08/28/2019



Photo # 2 - 05-087-07069



Location Name: Coral Production Corp. - Peterson E-2  
Inspection Date: 08/28/2019



Photo # 2 - 05-121-07069 - Oil stained soil at exhaust



Location Name: Coral Production Corp. - Peterson E-2  
Inspection Date: 08/28/2019



Photo # 3 - 05-121-07069 - Oil impacted soil near wellhead

Location Name: Coral Production Corp. - Peterson E-2  
Inspection Date: 08/28/2019



Photo # 4 - 05-121-07069 - Oil impacted soil near wellhead



Location Name: Coral Production Corp. - Peterson E-2  
Inspection Date: 08/28/2019



Photo # 4 - 05-121-07069 - Oil impacted soil near motor



Location Name: Coral Production Corp. - Peterson E-2  
Inspection Date: 08/28/2019



Photo # 4 - 05-121-07069 - Oil impacted soil near motor

