

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2019

Submitted Date:

08/28/2019

Document Number:

688305706

FIELD INSPECTION FORM

Loc ID 434358 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10706
Name of Operator: D90 ENERGY LLC
Address: 202 TRAVIS STREET #402
City: HOUSTON State: TX Zip: 77002

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President
Kosola, Jason		jason.kosola@state.co.us	
Spear, Sam	(970) 554-1988	sam@d90energy.com	All Inspections
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434359	WELL	PR	06/11/2015	OW	073-06552	BIG SKY 5-11	PR

General Comment:

Reinspection of the flowline spill on 8/24/2019 (see attached photos). Inspector requested that the landowner and LGD for Lincoln County also be contacted about the spill. Spill was contained and stained soils properly disposed of per operator. See attached photos of spill area after cleanup.

Form 19I and Form 4 VENT_FLARE are in process in the database.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		
PW/CO	WELLHEAD	>= 5 bbls		
Comment: <input type="text"/>				
Corrective Action: Contact COGCC EPS for further corrective actions.			Date:	<u>09/04/2019</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Inspected FacilitiesFacility ID: 434359 Type: WELL API Number: 073-06552 Status: PR Insp. Status: PR**Producing Well**Comment: PR.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402160686	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4923940
688305710	D90 Energy Big Sky 5-11 well and well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4923932
688305711	D90 Energy Big Sky 5-11 flowline at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4923933
688305712	D90 Energy Big Sky 5-11 spill area east of well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4923934
688305713	D90 Energy Big Sky 5-11 spill area looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4923935