

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2019

Submitted Date:

09/03/2019

Document Number:

689703493

**FIELD INSPECTION FORM**

Loc ID: 324176      Inspector Name: LONGWORTH, MIKE      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10163  
Name of Operator: NONSUCH NATURAL GAS INC  
Address: P O BOX 110066  
City: NAPLES      State: FL      Zip: 34108

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Edwards, Kent		kent.edwards@twaintheloop.com	
Lee, David	239-289-9046	dlee@nng.us.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261651	WELL	PR	10/16/2007	GW	045-07971	PUCKETT 797-1 1	PR
292477	PIT	AC	09/27/2007		-	PUCKETT 797-1	AC

**General Comment:**

COGCC Inspection Report Summary  
On Monday 09/03/2019 at approximately 1400 hrs, I, Inspector Mike Longworth, conducted a field inspection at Nonsuch Natural Gas Inc. Puckett 797-1-1, at Location # 324176 in Garfield County, Colorado  
During this inspection the following possible compliance issues were observed:  
The bigger of the 2 NFPA stickers is damaged. The NFPA stickers have conflicting Hazard levels.  
Install sign to comply with Rule 210.d.  
C.A. Date 11/04/2019  
Weeds around well head and around pit.  
Comply with Rule 603.f.  
C.A. Date 09/14/2019  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	The bigger of the 2 NFPA stickers is damaged. The NFPA stickers have conflicting Hazard levels.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 11/04/2019
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Access by Road 213 911		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds around well head and around pit.		
Corrective Action:	Comply with Rule 603.f.		Date: 09/14/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	PIT		
Comment:			

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical container at well head.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 261651 Type: WELL API Number: 045-07971 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 292477 Type: PIT API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Compaction						
Ditches	Pass					
Berms						
				Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Skimming/Settling      Lined: YES      Pit ID: 292477      Lat: 39.476540      Long: -108.167800

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: Adequate

Comment:

Corrective Action       Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Netting/Fence com      Fencing Condition: Adequate

Comment:

Corrective Action       Date: \_\_\_\_\_

**Netting:**

Netting Type: Fence/Net Combo      Netting Condition: Good

Comment:

Corrective Action       Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: YES      2+ feet Freeboard: YES

Comment:

Corrective Action       Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	292477	400783129	
	292477	1433721	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703494	Inspection 689703493 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927813">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927813</a>