

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2019

Submitted Date:

09/05/2019

Document Number:

689703498

FIELD INSPECTION FORM
 Loc ID 324312 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278163	WELL	PR	06/27/2006	GW	045-10842	PUCKETT 264-1	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 09/03/2019 at approximately 1630 hrs, I, Inspector Mike Longworth, conducted a field inspection at Caerus Piceance LLC Puckett 264-1 Location # 324312 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

No legal description on well sign.

Comply with Rule 210.b.

C.A. Date 11/06/2019

Weeds in tank containment berm.

Repair or install berms or other secondary containment devices per Rule 906.d.(1).

C.A. Date 10/06/2019

Damaged fence around tanks and separator.

Repair fencing.

C.A. Date 10/06/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	No legal description on well sign.		
Corrective Action:	Comply with Rule 210.b.	Date:	11/06/2019

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Damaged fence around tanks and separator.		
Corrective Action:	Repair fencing.	Date:	10/06/2019
Type	TANK BATTERY		
Comment:	Damaged fence around tanks and separator. Repair fencing. by 10/06/2019		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Weeds in tank containment berm.			

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).	Date:	10/06/2019
--------------------	--	-------	------------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	278163	Type:	WELL	API Number:	045-10842	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Compaction	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703504	Inspection 689703498 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928961