

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2019

Submitted Date:

09/04/2019

Document Number:

679601485

FIELD INSPECTION FORM

Loc ID 410128 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
302001	WELL	SI	03/01/2019	OW	123-30176	GREEN USX EE 13-15P	SI

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: Adequate

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: Weeds surrounding of pumpjack. See attached photos

Corrective Action: **Comply with Rule 603.f.**

Date: 09/14/2019

Type UNUSED EQUIPMENT

Comment: Unused equipment outside of pumpjack fencing. See attached photo.

Corrective Action: **Comply with Rule 603.f.**

Date: 10/04/2019

Overall Good:

Spills:

Type Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: Panel

Corrective Action:

Date:

Equipment:

corrective date

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 302001 Type: WELL API Number: 123-30176 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday, September 4, 2019 at approximately 13:47, I, Inspector Brittani Santistevan, conducted an on-site inspection at GREEN USX EE 13-15P (Noble Energy), at location #: 410128 in WELD COUNTY Colorado. While there, I observed a shut in pump jack. During this inspection the following possible compliance issues were observed: 1. Weeds surrounding pumpjack. COMPLY WITH RULE 603.F. (Corrective Action Date: September 14, 2019) See attached photo #3,4. 2. Unused equipment outside of pumpjack fencing. COMPLY WITH RULE 603.F. (Corrective Action Date: October 4, 2019) See attached photo #5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	09/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601486	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929047