

Inspection Photos  
Operator: Springdale Partners LLC  
Location: Springdale Unit 11 (Baney State 16-11)  
API #05-075-09268



1. Lease sign, Non working Emergency number

2. Unit, solar powered cathodic rectifier and vegetation

**Inspection Photos**  
**Operator: Springdale Partners LLC**  
**Location: Springdale Unit 11 (Baney State 16-11)**  
**API #05-075-09268**



**3. Engine shed in pile by unit, weeds**

**4. Steel panels, pipe and scrubber in weeds**