

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600152**FIELD INSPECTION FORM**
 Loc ID 312303 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10487Name of Operator: SPRINGDALE PARTNERS LLCAddress: 3409 MONTECLAIRE DRCity: SHERMAN State: TX Zip: 75092**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Stokes, Richard	903-815-4884	Richard.Stokes72@ymail.com	
Burn, Diana		diana.burn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221142	WELL	TA	08/01/2007	STOW	075-09268	SPRINGDALE UNIT BANEY STATE 16-11	TA

**General Comment:**

Follow up inspection. No effort has been made to correct abatements (603.f., 210.b., 326.) for inspection done 9/11/2017 doc #680001091, 7/2/2018 #68001787, 12/11/2018 #693600043.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Trail through farm ground.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Lease sign by well			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Invalid emergency contact number			
Corrective Action:	Install sign to comply with Rule 210.b.			Date: 08/09/2018
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Weeds around equipment and location			
Corrective Action:	Comply with Rule 603.f .			Date: 07/19/2018
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment and debris across location			
Corrective Action:	Comply with Rule 603.f .			Date: 08/09/2018
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Prime Mover	# 1			corrective date
Comment:	EA-30 Ajax engine (Incomplete) missing clutch, fan, starter			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	Gas scrubber, solar powered cathodic rectifier			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Conventional pumping unit			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 221142 Type: WELL API Number: 075-09268 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well is incapable of producing in present state, Well was required to pass a Mechanical Integrity Test by 4/30/2017.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Other	Pass	Other	Pass			

Comment: [Access is farmed over.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693600153	Inspection Photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929476">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929476</a>