

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600155**FIELD INSPECTION FORM**
 Loc ID 312297 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10487Name of Operator: SPRINGDALE PARTNERS LLCAddress: 3409 MONTECLAIRE DRCity: SHERMAN State: TX Zip: 75092**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Stokes, Richard	903-815-4884	Richard.Stokes72@ymail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221128	WELL	AC	11/10/1997	STOW	075-09254	SPRINGDALE 7	SI

**General Comment:**

Follow up inspection, No effort has been made to correct abatements (210.b., 603.f., 326) for inspections done 9/11/2017 #680001092, 7/2/2018 #680001785, 12/11/2018 #693600041

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Trail through farm ground		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by well, Sign does not display current operator		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/09/2018

Emergency Contact Number:			
Comment:	Invalid emergency contact number		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 08/09/2018

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Grass and weeds across location		
Corrective Action:	Comply with Rule 603.f .	Date:	07/19/2018

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Solar powered cathodic rectifier		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 221128 Type: WELL API Number: 075-09254 Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut in, Well was required to pass a Mechanical Integrity Test by 4/30/2017.. No effort has been made to correct abatements.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693600164	Inspection Photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929478">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929478</a>