

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600156**FIELD INSPECTION FORM**
 Loc ID 312147 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10487Name of Operator: SPRINGDALE PARTNERS LLCAddress: 3409 MONTECLAIRE DRCity: SHERMAN State: TX Zip: 75092**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Stokes, Richard	903-815-4884	Richard.Stokes72@ymail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219041	WELL	AC	03/28/1963	STOW	075-05861	SPRINGDALE STORAGE 2	TA

General Comment:

Follow up inspection, No effort has been made to correct abatements (210.b., 603.f., 326, Flowline risers) for inspections done 9/11/2017 #680001093, 7/2/2018 #680001784, 12/11/2018 #693600039

Location				
Lease Road:				
Type	Access			
comment:	2 Track through pasture			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign by well			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Stickers			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Invalid emergency contact number			
Corrective Action:	Install sign to comply with Rule 210.b.			Date: 08/09/2018
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds around equipment and across location			
Corrective Action:	Comply with rule 603.f.			Date: 07/19/2018
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Steel panels around wellhead			
Corrective Action:				Date:
Equipment:				
Type: FWKO	# 1			corrective date
Comment:	In a cement containment			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Steel ring containment			
Corrective Action:				Date:
Type: Horizontal Separator	# 1			
Comment:	In a metal shed			

Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:	6 unused, unmarked or locked out flowline risers.		
Corrective Action:	Unused or unmarked flowline risers (24 hrs to lock out tag out). 30 days to remove risers.	Date:	08/09/2018

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		40.664702,-103.299817
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Inadequate berms			
Corrective Action:	If facility is put back in use, berms must be repaired to contain volume of largest tank plus precipitation.			Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 219041 Type: WELL API Number: 075-05861 Status: AC Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well is incapable of production in present state, Well was required to pass a Mechanical Integrity Test by 4/30/2017. No effort has been made to correct abatements.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693600165	Inspection Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929479