

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600157

**FIELD INSPECTION FORM**

Loc ID 312150 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10487

Name of Operator: SPRINGDALE PARTNERS LLC

Address: 3409 MONTECLAIRE DR

City: SHERMAN State: TX Zip: 75092

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Burn, Diana     |              | diana.burn@state.co.us     |         |
| Stokes, Richard | 903-815-4884 | Richard.Stokes72@ymail.com |         |
| Pesicka, Conor  |              | conor.pesicka@state.co.us  |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 219050      | WELL | AC     | 03/10/1961  | STOW       | 075-05871 | SPRINGDALE 4  | SI          |

**General Comment:**

Follow up inspection, No effort has been made to correct abatements (210.b., 326) for inspections done 9/12/2017 #680001098, 7/2/2018 #680001778, 12/11/2018 #693600040

**Location****Lease Road:**

|                   |                         |       |  |
|-------------------|-------------------------|-------|--|
| Type              | Access                  |       |  |
| comment:          | 2 Track through pasture |       |  |
| Corrective Action | L                       | Date: |  |

Overall Good: ☐**Signs/Marker:**

|                    |                    |       |  |
|--------------------|--------------------|-------|--|
| Type               | WELLHEAD           |       |  |
| Comment:           | Lease sign by well |       |  |
| Corrective Action: |                    | Date: |  |

**Emergency Contact Number:**

Comment:

Corrective Action:  Date: 08/09/2018

**Good Housekeeping:**

|                    |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
| Type               | WEEDS                             |       |  |
| Comment:           | Grass around wellhead needs mowed |       |  |
| Corrective Action: |                                   | Date: |  |

Overall Good: ☐**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |                              |       |  |
|--------------------|------------------------------|-------|--|
| Type               | WELLHEAD                     |       |  |
| Comment:           | Steel panels around wellhead |       |  |
| Corrective Action: |                              | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**Facility ID: 219050 Type: WELL API Number: 075-05871 Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut in, Well was required to pass a Mechanical Integrity Test by 4/30/2017. No effort has been made to correct abatement.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Other            | Pass            | Other                   | Pass                  |               |                          |         |

Comment: [Access and location are partially grassed over.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description            | URL   |
|--------------|------------------------|---|
| 693600166    | Inspection Photographs | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929480">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929480</a> |