

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600159

FIELD INSPECTION FORM

Loc ID 312294 Inspector Name: QUINT, CRAIG On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10487
Name of Operator: SPRINGDALE PARTNERS LLC
Address: 3409 MONTECLAIRE DR
City: SHERMAN State: TX Zip: 75092

Findings:

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Stokes, Richard	903-815-4884	Richard.Stokes72@ymail.com	
Burn, Diana		diana.burn@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221121	WELL	TA	08/01/2007	STOW	075-09247	SPRINGDALE UNIT BANEY STATE 16-9	TA

General Comment:

Follow up inspection, No effort has been made to correct abatements (210.b., 603.f., 326) for inspections done 9/11/2017 #680001095, 7/2/2018 #680001781, 12/11/2018 #693600037

Location			
Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign by tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Invalid emergency contact number		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 08/09/2018
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around equipment and across location.		
Corrective Action:	Comply with rule 603.f.	Date:	07/19/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Steel panels		
Corrective Action:		Date:	
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:		Date:	
Type:	Deadman # & Marked	# 4	
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Elec panel, solar powered cathodic rectifier		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	160 United		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Elec motor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		40.658243,-103.296725
Comment:	Shared berm, 210 bbl steel water tank				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.658243,-103.296725
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 221121 Type: WELL API Number: 075-09247 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well was required to pass a Mechanical Integrity Test by 4/30/2017. No efforts have been made to correct abatements.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
		Other	Pass			

Comment: [Access farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	257875	880852	
	257875	880852	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693600168	Inspection Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929482