

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2019

Submitted Date:

09/05/2019

Document Number:

694900343

FIELD INSPECTION FORM

Loc ID 334571 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211470	WELL	PR	01/10/1998	GW	045-07230	SAVAGE 2-21	SI
275311	WELL	PR	06/16/2005	GW	045-13516	SAVAGE FEDERAL 2-5C (RE2)	SI
275312	WELL	PR	06/19/2005	GW	045-13515	SAVAGE FEDERAL 2-4D (RE2)	SI

General Comment:**COGCC Inspection Report Summary**

On Thursday 9/5/19 at approximately 1:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Savage RE2 Pad, at Location # 334571 in Garfield County, Colorado.

While there, I observed all wells shut in. Also there are two 300 BBL tanks one is out of service since 07/2011 the other one is locked out of service.

During this inspection the following possible compliance issues were observed:

Unused chemical pump in battery and unused stand for solar/battery

Unmarked dead man

(Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	911	Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused chemical pump in battery and unused stand for solar/battery		
Corrective Action:	remove all unused equipment	Date:	10/07/2019
Type	OTHER		
Comment:	Unmarked dead man		
Corrective Action:	Mark dead man	Date:	10/07/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type	#	Capacity	Type	Tank ID	SE GPS	corrective date
Type: Gas Meter Run	# 3					
Comment:						
Corrective Action:						Date:
Type: Horizontal Heated Separator	# 3					
Comment:						
Corrective Action:						Date:
Type: Plunger Lift	# 3					
Comment:						
Corrective Action:						Date:
Type: Bird Protectors	# 3					
Comment:						
Corrective Action:						Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:	1000 gallon tank is in battery containment				

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	one has been out of service since 07/2011 one is locked out of service				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 211470 Type: WELL API Number: 045-07230 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: well is closed at well head

Corrective Action: _____

Date: _____

Facility ID: 275311 Type: WELL API Number: 045-13516 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: well is closed at well head

Corrective Action: _____

Date: _____

Facility ID: 275312 Type: WELL API Number: 045-13515 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: well is closed at well head

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Ditches		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900346	694900343	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929857