

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2019

Submitted Date:

09/05/2019

Document Number:

694900338

FIELD INSPECTION FORM
 Loc ID 324423 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| , Caerus | | COGCC.inspections@caerus oilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 292166 | WELL | PR | 12/29/2007 | GW | 045-14610 | FEDERAL 11-15A(RJ11) | PR |

General Comment:**COGCC Inspection Report Summary**

On Thursday 9/5/19 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus federal RJ11 Pad, at Location # 324423 in Garfield County, Colorado.

While there, I observed Normal production operations.

This is a summary of inspection report.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Emergency Contact Number:**

| | | | |
|--------------------|-----|-------|--|
| Comment: | 911 | Date: | |
| Corrective Action: | | | |

Good Housekeeping:

| | | | |
|--------------------|--------|-------|--|
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|-----------------------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|------------------------------------|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| METHANOL | 1 | <50 BBLS | STEEL AST | | , |
| Comment: | 12 BBL tank in battery containment | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| | | | | |
|----------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 292166 | Type: WELL | API Number: 045-14610 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | producing | | | |
| Corrective Action: | | | | Date: |

| | | | | |
|--|--|--|--|--|
| | | | | |
|--|--|--|--|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | | Gravel | | | | |
| Berms | | Compaction | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 694900353 | 694900338 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929852 |