

Inspection Photos
Location Name: Energy Mineral Unit B#1
Location ID: 318873



Colorado Oil and Gas Conservation Commission
Sep 5, 2019 11:41:10

Photo 1 TNK BTRY



Colorado Oil and Gas Conservation Commission
Sep 5, 2019 11:42:50

Photo 2 Weeds and stained soil appear to have been removed.

Inspection Photos
Location Name: Energy Mineral Unit B#1
Location ID: 318873




Photo 3 Stained soil appears to have been removed from separator

Photo 4 Mechanical issues in separator house appear to not have been address pipes visibly leaking at time of inspection.

Inspection Photos
Location Name: Energy Mineral Unit B#1
Location ID: 318873



Photo 5 Stained soil appears to have been removed from crude oil tank load lines



Photo 6 OUT OF SERVICE on crude oil tanks appears to have been painted over

Inspection Photos
Location Name: Energy Mineral Unit B#1
Location ID: 318873



Photo 7 Produced water tank spill/ stained soil has not been addressed



Photo 8 Produced water tank it appears crew has started to hydrovac stained soil. At time of inspection stained soil and grey material are still present.

Inspection Photos
Location Name: Energy Mineral Unit B#1
Location ID: 318873



Photo 9 Produced water tank spill/ stained soil has not been addressed