

**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Pic 1**



**Pic 2 weeds**

**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Pic 3 stained soil/mechanical conditions**



**Pic 4**



**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Pic 5**



**Pic 6 weeds**

**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Pic 7 leak/spill**



**Pic 8 leak/spill**



**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Pic 9 trash/spill/leak**



**Pic 10 spill/leak**

**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Pic 11 spill/leak**



**Pic 12 stained soil/mechanical conditions**



**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Pic 13 weeds**



**Pic 14 hydrocarbons in pit / stained soil**

**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**



**Pic 15 hydrocarbons in pit/stained soil**



**Pic 16 weeds around manifold**



**Inspection Photos**  
**Location Name: Ferguson 2-25**  
**Location ID: 319714**

