

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/03/2019

Submitted Date:

09/06/2019

Document Number:

687905480**FIELD INSPECTION FORM**
 Loc ID 325164 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214178	WELL	SI	02/01/2017	OW	067-05498	LONG & SCHLUTER 1	SI

General Comment:

This is a workover inspection with plugging operations currently being conducted in accordance with Form 6 Well Abandonment Report Doc#402009810

Inspected Facilities									
Facility ID:	214178	Type:	WELL	API Number:	067-05498	Status:	SI	Insp. Status:	SI
Workover									
Comment:	<div>9-3-19 Plugging operations continued from 9-2-19: *Plug #3 (gallup top & 4.5" Liner Top) 2476'-2245' w/18 sxs cmt. *Plug #4 (Mancos) 1574'-1343' w/18 sxs cmt. *Pressure test casing (Pass) *Plug #4A (Mancos) 1574'-1343' w/18 sxs cmt. *Plug #5 (Mesaverde) 380'-280' w/18 sxs cmt. *Plug #6 (Mesaverde) 120'-0' w/18 sxs cmt.</div>								
Corrective Action:								Date:	