

Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 1. Overview of location taken at entrance facing southwest. No stormwater controls apparent.



Photo 2. Non-compacted perimeter berm, no stormwater controls apparent.



Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 3. Access road coming into location. No stormwater controls apparent.



Photo 4. Overview of location from northwest corner of disturbance looking southeast. No stormwater controls apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 5. Possible topsoil. No stormwater controls or topsoil protections apparent.



Photo 6. Overview of location from southwest corner looking southeast. No stormwater controls apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 7. South side of location. No stormwater controls apparent.



Photo 8. East side of location looking north. This is area designated for cuttings disposal onsite in Form 2. No stormwater controls apparent.



Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 9. Access road before drainage crossing. Dust from contractors vehicles and my own vehicle visible in photo. No stormwater controls apparent.



Photo 10. No stormwater controls apparent in drainage crossing.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 11. No stormwater controls apparent in drainage crossing.



Photo 12. Access road with no stormwater controls apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources