

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2019

Submitted Date:

09/06/2019

Document Number:

699300108

**FIELD INSPECTION FORM**

Loc ID 336435 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                | Comment         |
|--------------|-------|--------------------------------------|-----------------|
| Gomez, Jason |       | jason.gomez@state.co.us              |                 |
| ,            |       | Cogcc.inspections@crestone<br>pr.com | ALL INSPECTIONS |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 433920      | WELL | DG     | 05/01/2019  | LO         | 123-37846 | Kugel 1C-18H-H267 | DG          |

**General Comment:**

**Location****Lease Road:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | Access   |       |  |
| comment:           | Adequate |       |  |
| Corrective ActionL |          | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |                 |       |  |
|--------------------|-----------------|-------|--|
| Type               | DRILLING/RECOMP |       |  |
| Comment:           | Adequate        |       |  |
| Corrective Action: |                 | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |             |       |  |
|--------------------|-------------|-------|--|
| Type               | LOCATION    |       |  |
| Comment:           | Sound Walls |       |  |
| Corrective Action: |             | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 433920 Type: WELL API Number: 123-37846 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Ensign 153 Pusher/Rig Manager: Ryan Buford  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: \_\_\_\_\_

Comment: Current Depth 7,965 Ft.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

| Comment                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | User   | Date       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <p>COGCC Inspection Report Summary<br/>           On Friday 9/6/19 at approximately 1030 hrs., I, Inspector Robbie Revas,<br/>           Conducted an on-site inspection at the Kugel 1C-18H-H267 Crestone Peak, at<br/>           API # 05-123-37846 in Weld County Colorado.<br/>           While there, I observed Drilling Operation.<br/>           During this inspection no compliance issues were observed:<br/>           BOP test appeared to have passed, Chemical storage appeared to within containment.<br/>           Overall location appeared to be in compliance with COGCC rules<br/>           See attached photos.<br/>           Location is dry, weather is clear.<br/>           I spoke with Ryan Buford Company Man Crestone Peak and he updated me on operations<br/>           at time of inspection which was landing the curve at 7,965' getting ready to start drilling the<br/>           horizontal strech.<br/>           Routine inspection.<br/>           Continuing education COGCC Inspection Report Summary.<br/>           This is a summary of inspection report.</p> | revasr | 09/06/2019 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL                                                                                                                                                                 |
|--------------|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 699300109    | Location pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931098">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931098</a> |