

Inspection Photos
Operator: BP America
Location/API #: 067-07526
Date: 8-29-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southeastern edge facing westward.



Photo 3. View of bare and unstabilized soils within the southeastern project area. Stabilization/revegetation is needed here.



Photo 4. View of erosional channel within the eastern project area. Cobbles in channel are not adequate stormwater controls.



Photos 5 and 6. View of waste and debris observed within the southeastern project area.



Photo 7. View of unmarked rig anchor within the project area.



Photo 8. View of reference area facing eastward. Vegetation is comprised of pinyon juniper woodland.