

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2019

Submitted Date:

09/09/2019

Document Number:

699300118

FIELD INSPECTION FORM

Loc ID 328997 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248924	WELL	TA	04/12/2019	GW	123-16726	CLC RED W 15-15	PA

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 248924 Type: WELL API Number: 123-16726 Status: TA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: PA

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 9/9/19 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the CLC Red W #15-15 Kerr McGee, at API #05-123-16726 in Weld County Colorado.</p> <p>While there, I observed a PA wellsite.</p> <p>During this inspection no compliance issues were observed:</p> <p>CA per Doc. # 685100794 603.f unused equipment has been addressed</p> <p>Well report shows it to be TA at the time of this inspection the well appears to be PA,WH and all production equipment have been removed from wellsite and location appears to be in the process of being reclaimed.</p> <p>Form 6 was submitted on 9/27/2018 Doc. #401776782.</p> <p>Form 42 was submitted on 5/23/2019 Doc. # 402053478</p> <p>Form 42 (FLO) was submitted on 7/24/2019 Doc. # 402121326</p> <p>Location is dry, weather is clear.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	09/09/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300119	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4932578