

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/29/2019

Submitted Date:

08/29/2019

Document Number:

693501258**FIELD INSPECTION FORM**
 Loc ID 320463 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email                     | Comment            |
|--------------|-------|---------------------------|--------------------|
| Brown, Devin |       | dbrown@petrosharecorp.com |                    |
| Lloyd, Bill  |       | blloyd@petrosharecorp.com | Operations Manager |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 203824      | WELL | PR     | 03/01/2017  | GW         | 001-09384 | ZARLENGO 14-4 | PR          |

**General Comment:**

**Location**

|                    |                              |       |            |
|--------------------|------------------------------|-------|------------|
| <b>Lease Road:</b> |                              |       |            |
| Type               | Access                       |       |            |
| comment:           | Acess road covered in weeds. |       |            |
| Corrective Action: | Comply with rule 603 f       | Date: | 09/12/2019 |

Overall Good: ☐

|                      |  |       |  |
|----------------------|--|-------|--|
| <b>Signs/Marker:</b> |  |       |  |
| Type                 | TANK LABELS/PLACARDS   |       |  |
| Comment:             | Adequate but NFPA pacard on crude oil tank is fading may need to be repaced in near future |       |  |
| Corrective Action:   |  | Date: |  |
| Type                 | BATTERY  |       |  |
| Comment:             | Adequate   |       |  |
| Corrective Action:   |  | Date: |  |
| Type                 | WELLHEAD   |       |  |
| Comment:             | Adequate   |       |  |
| Corrective Action:   |  | Date: |  |

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WEEDS  |       |            |
| Comment:           | Weeds around well head and on entire location. |       |            |
| Corrective Action: | Comply with rule 603 f                         | Date: | 09/12/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |

|                                   |                                  |  |                 |
|-----------------------------------|----------------------------------|--|-----------------|
| <b>Equipment:</b>                 |                                  |  | corrective date |
| Type: Horizontal Heated Separator | # 1                              |  |                 |
| Comment:                          |                                  |  |                 |
| Corrective Action:                |                                  |  | Date:           |
| Type: Gas Meter Run               | # 1                              |  |                 |
| Comment:                          |                                  |  |                 |
| Corrective Action:                |                                  |  | Date:           |
| Type: Bird Protectors             | # 2                              |  |                 |
| Comment:                          |                                  |  |                 |
| Corrective Action:                |                                  |  | Date:           |
| Type: Bradenhead                  | # 1                              |  |                 |
| Comment:                          | Appears to be plumbed to surface |  |                 |
| Corrective Action:                |                                  |  | Date:           |
| Type: Plunger Lift                | # 1                              |  |                 |
| Comment:                          |                                  |  |                 |
| Corrective Action:                |                                  |  | Date:           |

**Tanks and Berms:**

| Contents           | # | Capacity | Type     | Tank ID | SE GPS |
|--------------------|---|----------|----------|---------|--------|
| PRODUCED WATER     | 1 | 100 BBLS | Open Top |         | ,      |
| Comment:           |   |          |          |         |        |
| Corrective Action: |   |          |          |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                                | Permeability (Wall) | Permeability (Base) | Maintenance |        |
|--------------------|---|---------------------|---------------------|-------------|--------|
|                    |   |                     |                     |             |        |
| Comment:           | Shares containment with crude oil tank. |                     |                     |             |        |
| Corrective Action: |   |                     |                     | Date:       |        |
| Contents           | #                                       | Capacity            | Type                | Tank ID     | SE GPS |
| CRUDE OIL          | 1                                       | 300 BBLS            | STEEL AST           |             | ,      |
| Comment:           |   |                     |                     |             |        |
| Corrective Action: |   |                     |                     |             |        |
| Corrective Action: |   |                     |                     |             |        |
| Date:              |   |                     |                     |             |        |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |  |
| Comment:           |          |                     |                     |             |  |
| Corrective Action: |          |                     |                     | Date:       |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 203824 Type: WELL API Number: 001-09384 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment

This is a follow up inspection per Doc#687400608. At time of inspection all previous corrective actions appear to be addressed.

At time of inspection new corrective actions have been observed.

Weeds: Rule 603 f Corrective action date of 9-12-19 See photos 1,2

I observed weeds on access road, well head and on entire location.

Weather conditions: Clear and location dry.

User

silverr

Date

08/29/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402164032    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927010">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927010</a> |
| 693501259    | loc pic              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927004">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927004</a> |