

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2019

Submitted Date:

08/29/2019

Document Number:

693501264

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
320264 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments4 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203289	WELL	PR	06/01/2019	GW	001-08798	MCELWAIN 4	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Electrical wiring and panel, conductor pipe and disassembled PU		
Corrective Action:	Comply with rule 603 f		Date: <u>09/29/2019</u>
Type	WEEDS		
Comment:	Weeds on location		
Corrective Action:	Comply with rule 603 f		Date: <u>09/12/2019</u>
Type	OTHER		
Comment:	Mechanical issues: Produced water tank load line and Piping inside separator house.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>09/29/2019</u>
Type	OTHER		
Comment:	Stained soil" under load line of produced water tank, inside separator under pipng.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: <u>09/29/2019</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:			Date:

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with crude oil tank				
Corrective Action:				Date:

Venting:				
Yes/No	YES			
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 203289 Type: WELL API Number: 001-08798 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Production flow lines on well head are closed at time of inspection well is SI.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday August 29, 2019 at approximately 12:20PM, I, Inspector Randy Silver, conducted an on-site inspection at KP Kauffman site McElwain #4, at API# 05-001-08798 in Adams County Colorado. While there, I observed a production well site During this inspection the following possible compliance issues were observed: Weeds: Rule 603 f Corrective action date of 9-12-19 See photos 4,5 Stained soil: Rule 907 e Corrective action date of 9-29-19 See photos 4,9 Unused equipment: Rule 603 f Corrective action date of 9-29-19 See photos 6,10 Mechanical issues: Rule 605 d Corrective action date of 9-29-19 See photos 9,10 At time of inspection I observed weeds on location, Unused PU, conductor pipe, unused wiring and panel. Stained soil under load line of produced water tank and inside separator with associated mechanical issues. Weather conditions: cloudy location dry. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	08/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402164035	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927013
693501265	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927007