

Inspection Photos
Location Name: 596-33C Pad
Location ID: #335880
Inspection Date: August 30, 2019



Photo #1 – Facility sign.

Photo #2 – Overview of location from southwest.



Inspection Photos
Location Name: 596-33C Pad
Location ID: #335880
Inspection Date: August 30, 2019



Photo #3 – Overview of fenced wellhead area from southeast. No localized accumulations of oil-stained soil were observed in wellhead area on inspection date.

Photo #4 – Close-up view of backfilled well cellars.

Note well cellars have been backfilled to prevent wildlife access.



Inspection Photos

Location Name: 596-33C Pad

Location ID: #335880

Inspection Date: August 30, 2019



Photo #5 – View of tank battery on north side of location.



Photo #6 – View inside of tank battery secondary containment on south side.



Inspection Photos
Location Name: 596-33C Pad
Location ID: #335880
Inspection Date: August 30, 2019



Photo #7 – Hoses stored on west side of tank battery secondary containment with metal fittings in direct contact with liner.



Photo #8 – Trailer pump on top of liner located west of tank battery.



Inspection Photos

Location Name: 596-33C Pad

Location ID: #335880

Inspection Date: August 30, 2019



Photo #9 – Unused, unmarked, and uncapped ¼” riser located northwest of tank battery. Operator was instructed to LO/TO and remove this riser in previous FIR (doc #690200036).



Photo #10 – Junk equipment and bucket located southeast of fenced separator area.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: 596-33C Pad
Location ID: #335880
Inspection Date: August 30, 2019



Photo #11 – Flowline risers north of separators have been LO/TO.

