

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2019

Submitted Date:

09/10/2019

Document Number:

694900365

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
334618 \_\_\_\_\_ Ramsey, Scott \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                     | Comment |
|--------------|-------|---|---------|
| , Caerus     |       | COGCC.inspections@caerus<br>oilandgas.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 280630      | WELL | PR     | 07/29/2008  | GW         | 045-11302 | MCU 26-8C (D25W) | PR          |
| 280631      | WELL | PR     | 09/20/2006  | GW         | 045-11301 | HMU 26-1C (D25W) | PR          |
| 291925      | WELL | PR     | 07/26/2008  | GW         | 045-14546 | HMU 25-3D(D25W)  | PR          |

**General Comment:**COGCC Inspection Report Summary

On Tuesday 9/10/19 at approximately 11:15 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Shideler D25W, at Location # 334618 in Garfield County, Colorado.

While there, I observed Normal production operations.

During this inspection the following possible compliance issues were observed:

Chemical tank at pigging station is missing labels.

(Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).

This is a summary of inspection report.

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective Action  |        |  | Date: |

Overall Good:

|                      |   |  |                  |
|----------------------|---|--|------------------|
| <b>Signs/Marker:</b> |   |  |                  |
| Type                 | TANK LABELS/PLACARDS                            |  |                  |
| Comment:             | chemical tank at pigging station missing labels |  |                  |
| Corrective Action:   | install proper labels                           |  | Date: 10/10/2019 |

|                                  |     |  |             |
|----------------------------------|-----|--|-------------|
| <b>Emergency Contact Number:</b> |     |  |             |
| Comment:                         | 911 |  |             |
| Corrective Action:               |     |  | Date: _____ |

|                           |        |  |       |
|---------------------------|--------|--|-------|
| <b>Good Housekeeping:</b> |        |  |       |
| Type                      | DEBRIS |  |       |
| Comment:                  |        |  |       |
| Corrective Action:        |        |  | Date: |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

|                    |           |  |       |
|--------------------|-----------|--|-------|
| <b>Fencing/:</b>   |           |  |       |
| Type               | LOCATION  |  |       |
| Comment:           | barb wire |  |       |
| Corrective Action: |           |  | Date: |

|                           |                                  |  |                 |
|---------------------------|----------------------------------|--|-----------------|
| <b>Equipment:</b>         |                                  |  | corrective date |
| Type: Bird Protectors     | # 3                              |  |                 |
| Comment:                  |                                  |  |                 |
| Corrective Action:        |                                  |  | Date:           |
| Type: Pig Station         | # 1                              |  |                 |
| Comment:                  |                                  |  |                 |
| Corrective Action:        |                                  |  | Date:           |
| Type: Ancillary equipment | # 1                              |  |                 |
| Comment:                  | chemical tank at pigging station |  |                 |
| Corrective Action:        |                                  |  | Date:           |
| Type: Plunger Lift        | # 3                              |  |                 |
| Comment:                  |                                  |  |                 |

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 3 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Gas Meter Run               | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 2 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                    |  |
|--------------------|--|
| Condition Adequate |  |
| Other (Content)    |  |
| Other (Capacity)   |  |
| Other (Type)       |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 280630 Type: WELL API Number: 045-11302 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 280631 Type: WELL API Number: 045-11301 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 291925 Type: WELL API Number: 045-14546 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Compaction              |                       |               |                          |         |
| Ditches          |                 | Ditches                 |                       |               |                          |         |
| Gravel           |                 | Culverts                |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 694900372    | 694900365   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4933546">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4933546</a> |