

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2019

Submitted Date:

09/04/2019

Document Number:

679705317

FIELD INSPECTION FORMLoc ID 316714 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74740

Name of Operator: RIO MESA RESOURCES INC

Address: P.O. BOX 984

City: RANGELY State: CO Zip: 81648

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Hayes, Mike	970-620-2257	hayespetro@centurytel.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232271	WELL	PR	12/01/2018	OW	103-40058	LUBAUER GOV'T 4	PR

General Comment:

COGCC Inspection Report Summary.

On 9-4-2019 at approximately 14:30, inspector Rick Moran, conducted a routine inspection at Rio Mesa Resources well Lubauer Government 4 in Rio Blanco county.

During this inspection the following compliance issues were observed:

1) 911 missing on well head sign. Photo 4. Complete by 10-4-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Note: Casing open to atmosphere. No gas odor detected. Photos 2 & 3.

This is a summary of inspection report 679705317.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing 911 on well head sign.

Corrective Action: Install sign to comply with Rule 210.b. Date: 10/04/2019

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 1			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:	Casing open to atmosphere. No gas odor detected.		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 232271	Type: WELL	API Number: 103-40058	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	Pump jack idle at time of inspection.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402166266	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928615
679705318	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928605