

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/30/2019

Submitted Date:

09/04/2019

Document Number:

688000335

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**General Comment:**

Environmental inspection related to nearby Complaint #200448016. There is a partially buried oil skim pit and a tinhorn (culvert) associated with Pit Facility ID 112069. Active Rem #9288 should be closed with a new eForm 27 describing the tinhorn closure plan. It is likely that the partially buried oil skim tank would need to be removed in order to facilitate closure of the tinhorn and it can be included in the same Form 27. Contact NE EPS Rob Young with any questions.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 112069Lat: 40.651460Long: -103.869821Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: 

A culvert (tinhorn) and partially buried oil skim tank are associated with Pit Facility ID 112069 and require closure under an approved eForm 27.

Corrective Action 

Submit an eForm 27 describing closure of the tinhorn and potentially the oil skim tank. Submit an eForm 27 requesting closure of Rem #9288 referencing the new remediation project number.

Date: 09/20/2019**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402166270	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928618">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928618</a>
688000337	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928609</a>