

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/03/2019

Submitted Date:

09/03/2019

Document Number:

689703493

FIELD INSPECTION FORM
 Loc ID 324176 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10163

Name of Operator: NONSUCH NATURAL GAS INC

Address: P O BOX 110066

City: NAPLES State: FL Zip: 34108

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-------------------------------|---------|
| Edwards, Kent | | kent.edwards@twaintheloop.com | |
| Lee, David | 239-289-9046 | dlee@nng.us.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 261651 | WELL | PR | 10/16/2007 | GW | 045-07971 | PUCKETT 797-1 1 | PR |
| 292477 | PIT | AC | 09/27/2007 | | - | PUCKETT 797-1 | AC |

General Comment:**COGCC Inspection Report Summary**

On Monday 09/03/2019 at approximately 1400 hrs, I, Inspector Mike Longworth, conducted a field inspection at Nonsuch Natural Gas Inc. Puckett 797-1-1, at Location # 324176 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

The bigger of the 2 NFPA stickers is damaged. The NFPA stickers have conflicting Hazard levels.

Install sign to comply with Rule 210.d.

C.A. Date 11/04/2019

Weeds around well head and around pit.

Comply with Rule 603.f.

C.A. Date 09/14/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | The bigger of the 2 NFPA stickers is damaged. The NFPA stickers have conflicting Hazard levels. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 11/04/2019 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Access by Road 213
911

Corrective Action:

Date:

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | Weeds around well head and around pit. | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 09/14/2019 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------|-------|--|
| Type | PIT | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |

| | | | |
|--------------------|--------------|-------|--|
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|----------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chemical container at well head. | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 261651 | Type: | WELL | API Number: | 045-07971 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 292477 | Type: | PIT | API Number: | - | Status: | AC | Insp. Status: | AC |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms | | | | | | |
| | | | | Material Handling And Spill Prevention | Pass | |
| Ditches | Pass | | | | | |
| Compaction | | | | | | |
| Compaction | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Skimming/SettlingLined: YESPit ID: 292477Lat: 39.476540Long: -108.167800Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: AdequateComment: Corrective Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Date: Anchor Trench Present: Oil Accumulation: YES2+ feet Freeboard: YESComment: Corrective Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 402165128 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927816 |
| 689703494 | Inspection 689703493 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927813 |