

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2019

Submitted Date:

09/04/2019

Document Number:

689703497

FIELD INSPECTION FORM

Loc ID 324395 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:
7 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274466	WELL	PR	12/28/2005	GW	045-13352	PUCKETT 24B-1	PR

General Comment:
 Follow Up Field inspection
 On Tuesday 09/03/2019 at approximately 1600 hrs, I, Inspector Mike Longworth, conducted a follow up field inspection at Caerus Piceance LLC, PUCKETT 24B-1, at Location # 324395 in Garfield County, Colorado
 All corrective actions have been addressed from 07/26/2019 Inspection # 689703394

 During this inspection the following possible compliance issues were observed:
 Well sign has no legal discription.
 Comply with Rule 210.b.(1)
 C.A. Date 11/04/2019
 300 bbl tank NFPA stickers have conflicting hazard levels. 200 bbl tank Produced water label is damaged.
 Comply with Rule 210.d.
 C.A. Date 11/04/2019
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign has no legal discription.		
Corrective Action:	Comply with Rule 210.b.(1)		Date: 11/04/2019
Type	TANK LABELS/PLACARDS		
Comment:	300 bbl tank NFPA stickers have conflicting hazard levels. 200 bbl tank Produced water label is damaged.		
Corrective Action:	Comply with Rule 210.d.		Date: 11/04/2019
Type	TANK LABELS/PLACARDS		
Comment:	Methanol tank meets Corrective action.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 274466 Type: WELL API Number: 045-13352 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Compaction	Pass			
Check Dams	Pass					
Ditches	Pass					
		Culverts	Pass			
		Ditches	Pass			
Check Dams	Pass					
		Check Dams	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402166667	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928968
689703503	Inspection 689703497 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928960