

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2019

Submitted Date:

09/05/2019

Document Number:

689703498

FIELD INSPECTION FORM

Loc ID 324312 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|---------------------------------------|---------------------------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 278163 | WELL | PR | 06/27/2006 | GW | 045-10842 | PUCKETT 264-1 | PR |

General Comment:

COGCC Inspection Report Summary
On Tuesday 09/03/2019 at approximately 1630 hrs, I, Inspector Mike Longworth, conducted a field inspection at Caerus Piceance LLC Puckett 264-1 Location # 324312 in Garfield County, Colorado
During this inspection the following possible compliance issues were observed:
No legal description on well sign.
Comply with Rule 210.b.
C.A. Date 11/06/2019
Weeds in tank containment berm.
Repair or install berms or other secondary containment devices per Rule 906.d.(1).
C.A. Date 10/06/2019
Damaged fence around tanks and separator.
Repair fencing.
C.A. Date 10/06/2019
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|------------------------------------|-------|------------|
| Type | WELLHEAD | | |
| Comment: | No legal description on well sign. | | |
| Corrective Action: | Comply with Rule 210.b. | Date: | 11/06/2019 |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--|-------|------------|
| Type | TANK BATTERY | | |
| Comment: | Damaged fence around tanks and separator. Repair fencing. by 10/06/2019 | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Damaged fence around tanks and separator. | | |
| Corrective Action: | Repair fencing. | Date: | 10/06/2019 |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------|---------|--------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|---------------------------------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Insufficient | Inadequate |
| Comment: | Weeds in tank containment berm. | | | |

| | | | |
|--------------------|--|-------|------------|
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 906.d.(1). | Date: | 10/06/2019 |
|--------------------|--|-------|------------|

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 278163 Type: WELL API Number: 045-10842 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |
| | | Compaction | Pass | | | |
| Compaction | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------------------|---|
| 402166671 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928970 |
| 689703504 | Insspection 689703498 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928961 |