

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600152**FIELD INSPECTION FORM**

Loc ID 312303 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10487Name of Operator: SPRINGDALE PARTNERS LLCAddress: 3409 MONTECLAIRE DRCity: SHERMAN State: TX Zip: 75092**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Burn, Diana | | diana.burn@state.co.us | |
| Stokes, Richard | 903-815-4884 | Richard.Stokes72@ymail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------------------|-------------|
| 221142 | WELL | TA | 08/01/2007 | STOW | 075-09268 | SPRINGDALE UNIT BANEY STATE 16-11 | TA |

General Comment:

Follow up inspection. No effort has been made to correct abatements (603.f., 210.b., 326.) for inspection done 9/11/2017 doc #680001091, 7/2/2018 #68001787, 12/11/2018 #693600043.

| Location | | | | |
|--|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Trail through farm ground. | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Lease sign by well | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | Invalid emergency contact number | | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | | | Date: 08/09/2018 |
| Good Housekeeping: | | | | |
| Type | WEEDS | | | |
| Comment: | Weeds around equipment and location | | | |
| Corrective Action: | Comply with Rule 603.f . | | | Date: 07/19/2018 |
| Type | UNUSED EQUIPMENT | | | |
| Comment: | Unused equipment and debris across location | | | |
| Corrective Action: | Comply with Rule 603.f . | | | Date: 08/09/2018 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Equipment: | | | | |
| Type: Prime Mover | # 1 | | | corrective date |
| Comment: | EA-30 Ajax engine (Incomplete) missing clutch, fan, starter | | | |
| Corrective Action: | | | | Date: |
| Type: Pump Jack | # 1 | | | |
| Comment: | Conventional pumping unit | | | |
| Corrective Action: | | | | Date: |
| Type: Ancillary equipment | # 2 | | | |
| Comment: | Gas scrubber, solar powered cathodic rectifier | | | |
| Corrective Action: | | | | Date: |
| Venting: | | | | |
| Yes/No | NO | | | |
| Comment: | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 221142 Type: WELL API Number: 075-09268 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well is incapable of producing in present state, Well was required to pass a Mechanical Integrity Test by 4/30/2017.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Other | Pass | Other | Pass | | | |

Comment: [Access is farmed over.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------|---|
| 402167306 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929487 |
| 693600153 | Inspection Photographs | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929476 |