

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600158

FIELD INSPECTION FORM

Loc ID 312260 Inspector Name: QUINT, CRAIG On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10487
Name of Operator: SPRINGDALE PARTNERS LLC
Address: 3409 MONTECLAIRE DR
City: SHERMAN State: TX Zip: 75092

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Stokes, Richard	903-815-4884	Richard.Stokes72@ymail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
220056	WELL	TA	08/01/2007	STOW	075-08176	SPRINGDALE STORAGE 5	TA

General Comment:

Follow up inspection, No effort has been made to correct abatements (210.b., 603.f., 326) for inspections done 9/11/2017 #680001094, 7/2/2018 #680001783, 12/11/2018 #693600038

Location			
Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by well		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Invalid emergency contact number		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 08/09/2018
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around equipment and across location		
Corrective Action:	Comply with rule 603.f.		Date: 07/19/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:			Date:
Type: FWKO	# 1		
Comment:	In a cement containment		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	In a metal shed		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Elec motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Elec panel		
Corrective Action:			Date:

Type: Other	# 1		
Comment:	Steel ring containment		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	160 Bethehem		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 220056 Type: WELL API Number: 075-08176 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is incapable of producing in present state, Well was required to pass a Mechanical Integrity Test by 4/30/2017. No effort has been made to correct abatements.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other	Pass			
Compaction	Pass	Compaction	Pass			

Comment: [Access is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402167313	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929492
693600167	Inspection Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929481