

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600160**FIELD INSPECTION FORM**

Loc ID 312149 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10487Name of Operator: SPRINGDALE PARTNERS LLCAddress: 3409 MONTECLAIRE DRCity: SHERMAN State: TX Zip: 75092**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------|
| Burn, Diana | | diana.burn@state.co.us | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Stokes, Richard | 903-815-4884 | Richard.Stokes72@ymail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 219049 | WELL | AC | 12/16/1992 | STOW | 075-05869 | SPRINGDALE STORAGE 1 | SI |

General Comment:

Follow up inspection, No effort has been made to correct abatements (210.b., 603.f., 326) for inspections done 9/12/2017 #680001099, 7/2/2018 #680001776, 12/11/2018 #693600047

Location

| | | | |
|--------------------|-------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | 2 Track through pasture | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|--------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by well | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|---|------------------|
| Emergency Contact Number: | | |
| Comment: | Invalid emergency contact number | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: 08/09/2018 |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weeds around equipment and across location. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 07/19/2018 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|------------------------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Steel panels around wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------|-------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Separator | # 1 | | |
| Comment: | In a metal shed | | |
| Corrective Action: | | Date: | |
| Type: FWKO | # 1 | | |
| Comment: | In a cement containment | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Steel ring containment | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------|----|--|--|
| Venting: | | | |
| Yes/No | NO | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 219049 Type: WELL API Number: 075-05869 Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in, Well was required to pass a Mechanical Integrity Test by 4/30/2017. No effort has been made to correct abatements.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------|---|
| 402167315 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929494 |
| 693600169 | Inspection Photographs | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929483 |