

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused methanol tank, and submersible pump equipment on location. see pic 1,2,3		
Corrective Action:	Comply with Rule 603.f .	Date:	11/12/2018
Type	WEEDS		
Comment:	Weeds throughout location see pics		
Corrective Action:	Comply with Rule 603.f .	Date:	09/15/2019

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:	LOTO		
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:	Surface equipment still on location		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202495 Type: WELL API Number: 001-07900 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: _____

Corrective Action: _____

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: _____ Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective _____

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: no netting/no fluid in pit

Corrective _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 9/5/19 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at Renegade Oil and Gas- API 001-07900 – Champlin 485 AMOCO 1 in Adams County Colorado. While there, I observed Shut In Well This is a follow up inspection from document # 688400397, 685100923 Corrective Actions are Delinquent All corrective actions from previous inspection document have been addressed except unused equipment on location. During this inspection the following possible compliance issues were observed: Unused methanol tank, and submersible pump equipment on location. see pic 1,2,3 Comply with Rule 603.f .11/12/18 Weeds throughout location see pics Comply with Rule 603.f .9/15/19 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	09/05/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402168108	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4930118
699500025	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4930113