

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2019

Submitted Date:

09/06/2019

Document Number:

699500031

**FIELD INSPECTION FORM**

Loc ID 320469 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 95620  
Name of Operator: WESTERN OPERATING COMPANY  
Address: 1165 DELAWARE STREET #200  
City: DENVER State: CO Zip: 80204

**Findings:**

- 9 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
, COGCC		conor.pesicka@state.co.us	
Chesson, Robert		robert.chesson@state.co.us	
,		dnr_cogccenforcement@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
James, Steven D	(303) 893-2438	steve@westernoperating.com	<a href="#">All Inspections</a>
Burn, Diana		diana.burn@state.co.us	
Hart, Dale	719-688-1638	dale@westernoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256059	WELL	PR	10/11/2010	OW	001-09397	LINNEBUR 6-13	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	no netting around open flame on verticle heated separator flame see pic 8		
Corrective Action:	Install or repair wildlife protection equipment per rule 324 A.a	Date:	09/16/2019
Type	OTHER		
Comment:	mechanical conditions around load lines, mechanical conditions in separator house see pic 6,9		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/05/2019
Type	OTHER		
Comment:	Stained soil near load lines by tanks, and inside separator house see pic 6,9		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	10/05/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,

Comment:						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shares contianment with oil tanks				
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		39.826350,-104.151620	
Comment:						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No						
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type	Ignitor/Combustor					
Comment:		What appears to be all gas coming into location being flared. Gas meter run is not on location, and pipeline is LOTO				
Corrective Action:		Contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.			Date: 09/06/2019	

**Inspected Facilities**

Facility ID: 256059 Type: WELL API Number: 001-09397 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Environmental**

**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: 20  
Comment: What appears to be leaking flowline going from the separator to the oil tanks see pic 1,2,3,4  
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Date: 09/05/2019  
Reportable: YES GPS: Lat 39.826380 Long -104.151560  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_  
Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On 9/5/19 at approximately 1400 I, Inspector Justin Medina conducted an on-site inspection at Western Operating Company- API 001-09397 –Linnebur 6-13 in Adams County Colorado.</p> <p>While there, I observed Producing well                      During this inspection the following possible compliance issues were observed:                      Stained soil near load lines by tanks, and inside separator house see pic 6,9                      Properly treat or dispose of oily waste in accordance with 907.e 10/5/19                      mechanical conditions around load lines, mechanical conditions in separator house see pic 6,9                      Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.10/5/19                      no netting around open flame on verticle heated separator flame see pic 8                      Install or repair wildlife protection equipment per rule 324 A.a 9/16/19                      What appears to be leaking flowline going from the separator to the oil tanks see pic 1,2,3,4                      Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. 9/5/19                      What appears to be all gas coming into location being flared. Gas meter run is not on location, and pipeline is LOTO                      Contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details. 9/6/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	medinaj	09/06/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402168110	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4930119">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4930119</a>
699500032	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4930116">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4930116</a>