

Inspection Photos
Location Name: NW Corner of Weld County Roads 12 & 11
Spill/Release: 467047



Excavation to expose failed section of flowline.

HDPE pipe being stung/slipped into carbon steel line.

Inspection Photos
Location Name: Weld County Roads 12 & 11
Spill/Release: 467047



Excavation to expose failed section of flowline.



Failed section of flowline.

Inspection Photos
Location Name: Weld County Roads 12 & 11
Spill/Release: 467047



Failed section of flowline.



View into open excavation.

