

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2019

Submitted Date:

09/13/2019

Document Number:

699700003**FIELD INSPECTION FORM**

Loc ID 334451 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	
Fischer, Alex		alex.fischer@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Arauza, Steven		steven.arauza@state.co.us	

General Comment:

On September 4, 2019, COGCC Environmental Staff (John Heil and Steven Arauza) conducted an environmental field inspection of LARAMIE ENERGY LLC (Laramie operator #10433) Laramie NVega 1D Location ID 334451 Spill ID 467076.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Active gas leak from a valve on the north side of Delta 27-321 (077-09334) wellhead. Operator was notified via cell phone on 9/4/2019.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	09/14/2019

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 10

Comment: COGCC staff observed a 45 feet by 45 feet by 3 feet deep excavation where the tank battery was located (northwest side of the pad, see photos). At time of inspection, Operator was on location delineating the spill with a PID while a mini excavator removed the impacted material. Operator indicated that the impacted material was being hauled off and that the stockpiled soil on location is clean and will be used backfilling the excavation. Operator discovered additional impacted soil around a flowline riser to the north of the tank battery. Operator shall comply with COAs on Doc# 402167798.

Corrective Action:

Date:

Reportable: YES

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Comment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700022	20190904 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937111