

Inspection Photos

API: 05-071-06340

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/12/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06340 | Date: 9/12/2019

Inspection Photos



Photo 1. Facing northwest near the mouth of the canyon. The main road has recently be graded. Erosion is occurring along the side of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 9/12/2019

Inspection Photos



Photo 2. Sediment has already filled into the diversion ditch since grading occurred. No work has been conducted here since previous inspection. Erosion must be controlled to prevent sediment discharge. This area of disturbance needs to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 9/12/2019

Inspection Photos



Photo 3. The rock check dams were not installed correctly. Stormwater is flowing around the checkdams causing erosion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 9/12/2019

Inspection Photos



Photo 4. Photo of another checkdam further along the road. The rock check dams were not installed correctly. Stormwater is flowing around the checkdams causing erosion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 9/12/2019

Inspection Photos



Photo 5. Photo of another checkdam further along the road. The rock check dam has filled in with sediment. Erosion needs to be controlled from the source.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 9/12/2019