

# Inspection Photos

API: 05-071-06130

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/12/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-06130 | Date: 9/12/2019

## Inspection Photos



**Photo 1.** The culvert has filled in with sediment along the main road.

Lat/Long:37.09153/-104.93557



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 9/12/2019



## Inspection Photos



**Photo 2.** The culvert has filled in with sediment along the main road.

Lat/Long:37.09183/-104.93794



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 9/12/2019



## Inspection Photos



**Photo 3.** The culvert has been cleaned out since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 9/12/2019



## Inspection Photos



**Photo 4.** The road has been repaired and the culvert cleaned out.  
Lat/Long:37.09015/-104.94924



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 9/12/2019

## Inspection Photos



**Photo 5.** The culvert was cleaned out to allow drainage water to flow through the culvert.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 9/12/2019



## Inspection Photos



**Photo 6.** Facing west toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 9/12/2019