

Inspection Photos

API: 05-071-07186

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/12/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07186 | Date: 9/12/2019

Inspection Photos



Photo 1. There is soil sloughing that occurred at the east side of the location. Corrective action of the previous inspection was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07186 | Date: 9/12/2019

Inspection Photos



Photo 2. Facing toward the location fill slope. There are numerous noxious weeds growing in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07186 | Date: 9/12/2019

Inspection Photos



Photo 3. There are numerous noxious weeds growing in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07186 | Date: 9/12/2019